

Date	January 25, 2006	Sampling Conditions*			Wet							
Site ID	Location	Ammonia	Nitrate/Nitrite	ortho-Phosphate	Total Nitrogen	Total Phosphorus	Suspended Solids	Conductivity	Diss. Oxygen	pH	Temperature	
BEB025	Beaver Brook @ Maskwonicut	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
BMB026	Beaver Meadow Brook @ Pine Street	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
EAB010	East Branch @ Neponset Street	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Non-Support	Support	
GEB020	Germany Brook @ inlet of Ellis Pond	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
HAB002	Hawes Brook @ Walpole Street	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
HAB006	Hawes Brook @ Endean Park, railroad bridge	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Problem	no data	1999-29	Support	
HAB010	Hawes Brook @ Washington Street	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Problem	Support	Support	Support	
MEB001	Meadow Brook @ Sunnyside Road	no data	no data	no data	no data	no data	no data	no data	Support	no data	no data	
MIB030	Mine Brook @ Nebo Street	Acceptable	Acceptable	Acceptable	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
MLB024	Mill Brook @ inlet of Petee's Pond	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	1999-03	Support	
MOB001	Mother Brook @ Washington Street	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
MOB032	Mother Brook @ Reservation	no data	no data	no data	no data	no data	no data	no data	Support	no data	no data	
MPB037	Massapoag Brook @ Billings Street	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
MPB088	Massapoag Brook @Walnut Street	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER002	Neponset River @ outlet of Crackrock Pond	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER040	Neponset River @ South Street	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER075	Neponset River @ Hollingsworth & Vose Dam	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER080	Neponset River @ Pleasant Street Bridge	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
NER125	Neponset River @ Dedham Street Bridge	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER150	Neponset River @ Paul's Bridge	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
NER165	Neponset River @ Fairmount Avenue	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
NER185	Neponset River @ Ryan Playground	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
NER200	Neponset River @ Adams Street Bridge	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
PEB008	Pecunit Brook @ Elm Street	Acceptable	Acceptable	Concern	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
POB040	Ponkapoag Brook @ Elm St	Acceptable	Acceptable	Acceptable	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support	
PQB036	Pequit Brook @ Rt 138	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
PQB040	Pequit Brook @ Sherman Street	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
PTB028	Pine Tree Brook @ Blue Hills Parkway	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	no data	
PTB035	Pine Tree Brook @ Brook Road	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
PTB047	Pine Tree Brook @ Central Avenue	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
PUB022	Purgatory Brook @ Rt 1A, near Everett St	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
SHB021	Steep Hill Brook @ Central St & West St	Acceptable	Problem	Concern	Problem	Acceptable	Acceptable	Problem	Support	Support	Support	
SMB001	School Meadow Brook @ Pine Street	no data	no data	no data	no data	no data	no data	no data	Support	no data	no data	
SPB016	Spring Brook @ Route 27	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
THB033	Traphole Brook @ Sumner Street	Acceptable	Acceptable	Concern	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support	
TUR001	Turner's Pond	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support	
UNB002	Unquity Brook @ Randolph Avenue	Acceptable	Problem	Concern	Problem	Acceptable	Acceptable	Problem	Support	Support	Support	
UNB014	Unquity Brook @ Adams Street	no data	no data	no data	no data	no data	no data	no data	Support	no data	no data	
UNB016	Unquity Brook @ Squantum St/Christopher Rd	no data	no data	no data	no data	no data	no data	no data	Support	no data	no data	
WIP002	Willet Pond, east end	no data	no data	no data	no data	no data	no data	no data	no data	no data	no data	
WIP003	Willet Pond, southern site	no data	no data	no data	no data	no data	no data	no data	no data	no data	no data	

*Sampling Conditions

Greater than or equal to 0.05" / 72 hours = wet

Less than 0.05" / 72 hours = dry