

Date	May 14, 2008	Sampling Conditions*		dry						
Site ID	Location	E. Coli	Total Phosphorus	Total Nitrogen	ortho-Phosphate	Ammonia	Conductivity	Diss. Oxygen	pH	Temperature
BEB025	Beaver Brook @ Maskwonicut	Support	Acceptable				Acceptable	Support	Support	Support
BMB026	Beaver Meadow Brook @ Pine Street	Support	Acceptable				Acceptable	Support	Support	Support
EAB010	East Branch @ Neponset Street	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
GEB020	Germany Brook @ inlet of Ellis Pond	Support	Acceptable				Problem	Support	Support	Support
HAB002	Hawes Brook @ Walpole Street	Support	Acceptable				Acceptable	Support	Support	Support
HAB006	Hawes Brook @ Endean Park, railroad bridge	Support	Acceptable				Acceptable	no data	Support	Support
HAB010	Hawes Brook @ Washington Street	Support	Acceptable	Problem	Acceptable	Acceptable	Acceptable	Support	Support	Support
MEB001	Meadow Brook @ Sunnyside Road	Non-support	Problem				Problem	Support	Support	Support
MIB030	Mine Brook @ Nebo Street	Support	Acceptable				Acceptable	Support	Non-Support	Support
MLB024	Mill Brook @ inlet of Petee's Pond	Support	Acceptable				Acceptable	Support	Support	Support
MMB106	Turner's Pond at Mill Pond Rd.	Non-support	Acceptable		Concern	Acceptable	Acceptable	Support	Support	Support
MOB001	Mother Brook @ Washington Street	Support	Acceptable	Problem	Concern	Acceptable	Acceptable	Support	Support	Support
MOB032	Mother Brook @ Reservation	Support	Acceptable				Acceptable	Support	Support	Support
MPB037	Massapoag Brook @ Billings Street	Support	Acceptable				Acceptable	Support	Support	Support
MPB088	Massapoag Brook @Walnut Street	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
NER002	Neponset River @ outlet of Crackrock Pond	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
NER040	Neponset River @ South Street	Support	Acceptable				Acceptable	Support	Support	Support
NER075	Neponset River @ Hollingsworth & Vose Dam	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
NER080	Neponset River @ Pleasant Street Bridge	Support	Acceptable				Acceptable	Support	Support	Support
NER125	Neponset River @ Dedham Street Bridge	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
NER150	Neponset River @ Paul's Bridge	Support	Acceptable	Problem	Concern	Acceptable	Acceptable	Support	Support	Support
NER165	Neponset River @ Fairmount Avenue	Support	Acceptable				Acceptable	Support	Support	Support
NER185	Neponset River @ Ryan Playground	Support	Acceptable				Acceptable	Support	Support	Support
NER200	Neponset River @ Adams Street Bridge	Support	Acceptable	Acceptable	Acceptable	Acceptable	Acceptable	Support	Support	Support
PEB008	Pecunit Brook @ Elm Street	Support	Acceptable				Acceptable	Support	Support	Support
POB040	Ponkapoag Brook @ Elm St	Support	Acceptable		Concern	Acceptable	Acceptable	Support	Support	Support
PQB036	Pequit Brook @ Rt 138	Support	Acceptable		Acceptable	Acceptable	Acceptable	Non-Support	Support	Support
PQB040	Pequit Brook @ Sherman Street	Support	Acceptable				Acceptable	Support	Support	Support
PTB028	Pine Tree Brook @ Blue Hills Parkway	Support	Acceptable	Acceptable	Acceptable	no data	Acceptable	Support	Support	Support
PTB035	Pine Tree Brook @ Brook Road	Support	Acceptable				Acceptable	Support	Support	Support
PTB047	Pine Tree Brook @ Central Avenue	no data	no data	no data	no data	no data	no data	Support	no data	no data
PUB022	Purgatory Brook @ Rt 1A, near Everett St	Support	Acceptable		Acceptable	Acceptable	Acceptable	Support	Support	Support
SHB021	Steep Hill Brook @ Central St & West St	Support	Acceptable				Acceptable	Support	Support	Support
SMB001	School Meadow Brook @ Pine Street	Support	Acceptable				Acceptable	Support	Support	Support
SPB016	Spring Brook @ Route 27	Support	Acceptable				Problem	Support	Support	Support
THB033	Traphole Brook @ Sumner Street	Support	Acceptable	Acceptable	Acceptable	Acceptable	Problem	Support	Support	Support
UNB002	Unquity Brook @ Randolph Avenue	Support	Acceptable				Problem	Non-Support	Support	Support
UNB014	Unquity Brook @ Adams Street	Non-support	Acceptable				Problem	Support	Support	Support
UNB016	Unquity Brook @ Squantum St/Christopher Rd	Non-support	Acceptable				Problem	Support	Support	Support
WIP002	Willett Pond, east end	Support	Acceptable				Acceptable	no data	Support	Support
WIP003	Willett Pond, southern site	Support	Acceptable				Acceptable	no data	Support	Support

*Sampling Conditions

Greater than or equal to 0.05" / 72 hours = wet

Less than 0.05" / 72 hours = dry

	Problem or Non-support
	Concern
	Acceptable or Support
	No data